

THEORY OF METAL CUTTING & TOOL DESIGN

UNIT I THEORY OF METAL CUTTING

8 hrs.

General motion of machine tools – Classifications of metal cutting – Mechanics of metal cutting – Chip formation – Specific cutting energy – Nomenclature of cutting tools – Shear angle theory of merchant, Lee and Shaffer – Temperature in metal cutting – Measurement of cutting temperature .


UNIT – I THEORY OF METAL CUTTING

INTRODUCTION

In an industry, metal components are made into different shapes and dimensions by using various metal working processes.

Metal working processes are classified into two major groups. They are:

Non-cutting shaping or chips less or metal forming process - forging, rolling, pressing, etc. Cutting shaping or metal cutting or chip forming process - turning, drilling, milling, etc.



MATERIAL REMOVAL PROCESSES

Definition and principle of machining

Machining is an essential process of finishing by which work pieces are produced to the desired dimensions and surface finish by gradually removing the excess material from the preformed blank in the form of chips with the help of cutting tool(s) moved past the work surface(s).

Fig. 1 typically illustrates the basic principle of machining. A metal rod of irregular shape, size and surface is converted into a finished product of desired dimension and surface finish by machining by proper relative motions of the tool-work pair.




Fig. 1 Principle of machining (Turning)




Fig. 2 Requirements for machining

Purpose of machining

Most of the engineering components such as gears, bearings, clutches, tools, screws and nuts etc. need dimensional and form accuracy and good surface finish for serving their purposes. Performing like casting, forging etc. generally cannot provide the desired accuracy and finish. For that such preformed parts, called blanks, need semi-finishing and finishing and it is done by machining and grinding. Grinding is also basically a machining process.

Machining to high accuracy and finish essentially enables a product:

Fulfill its functional requirements. Improve its performance. Prolong its service.

Requirements of machining

The essential basic requirements for machining a work are schematically illustrated in Fig. 2. The blank and the cutting tool are properly mounted (in fixtures) and moved in a powerful device called machine tool enabling gradual removal of layer of material from the work surface resulting in its desired dimensions and surface finish. Additionally some environment called cutting fluid is generally used to ease machining by cooling and lubrication.

Types of cutting tools

Cutting tools may be classified according to the number of major cutting edges (points) involved as follows:

Single point: e.g., turning tools, shaping, planing and slotting tools and boring tools.

Double (two) point: e.g., drills.

Multipoint (more than two): e.g., milling cutters, broaching tools, hobs, gear shaping cutters etc.

Nomenclature/Geometry of single point cutting (turning) tools

Both material and geometry of the cutting tools play very important roles on their performances in achieving effectiveness, efficiency and overall economy of machining.

Concept of rake and clearance angles of cutting tools

The word tool geometry is basically referred to some specific angles or slope of the salient faces and edges of the tools at their cutting point. Rake angle and clearance angle are the most significant for all the cutting tools. The concept of rake angle and clearance angle will be clear from some simple operations shown in Fig. 3.





Fig.3 Rake and clearance angles of cutting tools

Definition

Rake angle (γ): Angle of inclination of rake surface from reference plane.

Clearance angle (α): Angle of inclination of clearance or flank surface from the finished surface.

Rake angle is provided for ease of chip flow and overall machining. Rake angle may be positive, or negative or even zero as shown in Fig. 1.4 (a, b and c).



(a) Positive rake (b) Zero rake (c) Negative rake

Fig. 4 Three possible types of rake angles

Relative advantages of such rake angles are:

Positive rake - helps reduce cutting force and thus cutting power requirement. Zero rake - to simplify design and manufacture of the form tools.

Negative rake - to increase edge-strength and life of the tool.

Clearance angle is essentially provided to avoid rubbing of the tool (flank) with the machined surface which causes loss of energy and damages of both the tool and the job surface. Hence, clearance angle is a must and must be positive ($3^{\circ} \sim 15^{\circ}$) depending upon tool-work materials and type of the machining operations like turning, drilling, boring etc.

Systems of description of tool geometry

Tool-in-Hand System - where only the salient features of the cutting tool point are identified or visualized as shown in Fig. 5 (a). There is no quantitative information, i.e., value of the angles.

- Machine Reference System - ASA system.
- Tool Reference System - Orthogonal Rake System - ORS.
- Normal Rake System - NRS.
- Work Reference System - WRS.

Description of tool geometry in Machine Reference System

This system is also called as ASA system; ASA stands for American Standards Association.

Geometry of a cutting tool refers mainly to its several angles or slopes of its salient working surfaces and cutting edges. Those angles are expressed with respect to some planes of reference.

In Machine Reference System (ASA), the three planes of reference and the coordinates are chosen based on the configuration and axes of the machine tool concerned. The planes and axes used for expressing tool geometry in ASA system for turning operation are shown in Fig. 5 (b).




Fig 5 (a) Basic features of single point cutting (turning) tool




Fig. 5 (b) Planes and axes of reference in ASA system

The planes of reference and the coordinates used in ASA system for tool geometry are:

$\pi_R - \pi_X - \pi_Y$ and $X_m - Y_m - Z_m$; where,

π_R = Reference plane; plane perpendicular to the velocity vector. Shown in Fig. 1.5 (b).

π_X = Machine longitudinal plane; plane perpendicular to π_R and taken in the direction of assumed longitudinal feed.

π_Y = Machine transverse plane; plane perpendicular to both π_R and π_X . [This plane is taken in the direction of assumed cross feed]

The axes X_m, Y_m and Z_m are in the direction of longitudinal feed, cross feed and cutting velocity (vector) respectively. The main geometrical features and angles of single point tools in ASA systems and their definitions will be clear from Fig. 6.





Fig. 6 Tool angles in ASA system



Definition of:

Shank: The portion of the tool bit which is not ground to form cutting edges and is rectangular in cross section. [Fig. 1.5 (a)]

Face: The surface against which the chip slides upward. [Fig. 1.5 (a)]

Flank: The surface which face the work piece. There are two flank surfaces in a single point cutting tool. One is principal flank and the other is auxiliary flank. [Fig. 1.5 (a)]

Heel: The lowest portion of the side cutting edges. [Fig. 1.5 (a)]

Nose radius: The conjunction of the side cutting edge and end cutting edge. It provides strengthening of the tool nose and better surface finish. [Fig. 1.5 (a)]

Base: The underside of the shank. [Fig. 1.5 (a)]

Rake angles: [Fig. 6]

γ_x = Side rake angle (axial rake): angle of inclination of the rake surface from the reference plane (π_R) and measured on machine reference plane, π_X .

γ_y = Back rake angle: angle of inclination of the rake surface from the reference plane and measured on machine transverse plane, π_Y .

Clearance angles: [Fig. 6]

α_x = Side clearance angle (Side relief angle): angle of inclination of the principal flank from the machined surface (or CV) and measured on π_X plane.

α_y = Back clearance angle (End relief angle): same as α_x but measured on π_Y plane.

Cutting angles: [Fig. 6]

ϕ_s = Side cutting edge angle (Approach angle): angle between the principal cutting edge (its projection on π_R) and π_Y and measured on π_R .

ϕ_e = End cutting edge angle: angle between the end cutting edge (its projection on π_R) from π_X and measured on π_R .

Designation of tool geometry

The geometry of a single point tool is designated or specified by a series of values of the salient angles and nose radius arranged in a definite sequence as follows:

Designation (Signature) of tool geometry in ASA System - $\gamma_y, \gamma_x, \alpha_y, \alpha_x, \phi_e, \phi_s, r$ (in inch)

Example: A tool having 7, 8, 6, 7, 5, 6, 0.1 as designation (Signature) in ASA system will have the following angles and nose radius.

Back rake angle	=	7°
Side rake angle	=	8°
Back clearance angle	=	6°
Side clearance angle	=	7°
End cutting edge angle	=	5°
Side cutting edge angle	=	6°
Nose radius	=	0.1 inch


Tool signature

American System

For example a tool may designated in the following sequence:

8-14-6-6-6-15-1

1. Back rake angle is 8
2. Side rake angle is 14
3. End relief angle is 6
4. Side relief angle is 6
5. End cutting Edge angle is 6
6. Side cutting Edge angle is 15
7. Nose radius is 1 mm



Tool Geometry

Tool	Abbreviation	Angle Recommended
Back rake	BR	12°
Side rake	SR	12°
End relief	ER	10°
Side relief	SRF	10°
End cutting edge angle	ECEA	30°
Side cutting edge angle	SCEA	15°
Nose radius	NR	$\frac{1}{32}$ in.

Types of metal cutting processes

The metal cutting process is mainly classified into two types. They are:

Orthogonal cutting process (Two - dimensional cutting) - The cutting edge or face of the tool is 90^0 to the line of action or path of the tool or to the cutting velocity vector. This cutting involves only two forces and this makes the analysis simpler.

Oblique cutting process (Three - dimensional cutting) - The cutting edge or face of the tool is inclined at an angle less than 90^0 to the line of action or path of the tool or to the cutting velocity vector. Its analysis is more difficult of its three dimensions.

Orthogonal and oblique cutting

It appears from the diagram shown in Fig. 7 (a and b) that while turning ductile material by a sharp tool, the continuous chip would flow over the tool's rake surface and in the direction apparently perpendicular to the principal cutting edge, i.e., along orthogonal plane which is normal to the cutting plane containing the principal cutting edge. But practically, the chip may not flow along the orthogonal plane for several factors like presence of inclination angle, λ , etc.

The role of inclination angle, λ on the direction of chip flow is schematically shown in Fig. 8 which visualizes that: When $\lambda = 0^0$, the chip flows along orthogonal plane, i.e, $\rho_c = 0^0$.

When $\lambda \neq 0^0$, the chip flow is deviated from π_o and $\rho_c = \lambda$ where ρ_c is chip flow deviation (from π_o) angle.





Fig. 7 (a) Setup of orthogonal and oblique cutting turning.

Fig. 7 (b) Ideal direction of chip flow in




Fig. 8 Role of inclination angle, λ on chip flow direction

Orthogonal cutting: When chip flows along orthogonal plane, π_o , i.e., $\rho_c = 0^0$.

Oblique cutting: When chip flow deviates from orthogonal plane, i.e. $\rho_c \neq 0^0$.

But practically ρ_c may be zero even if $\lambda = 0^0$ and ρ_c may not be exactly equal to λ even if $\lambda \neq 0^0$. Because there is some other (than λ) factors also may cause chip flow deviation.

Pure orthogonal cutting

This refers to chip flow along π_o and $\phi = 90^0$ as typically shown in Fig. 9. Where a pipe like job of uniform thickness is turned (reduced in length) in a center lathe by a turning tool of geometry; $\lambda = 0^0$ and $\phi = 90^0$ resulting chip flow along π_o which is also π_x in this case.




Fig. 9 Pure orthogonal cutting (pipe turning)

Comparison between Orthogonal and oblique cutting

Orthogonal Cutting

- The cutting edge of the tool remains normal to the direction of *tool feed* or *work feed*.
- The direction of chip flow velocity is normal to the cutting edge of the tool. (*chip flow angle*)
- The angle of inclination 'i' of the cutting edge of the tool with the normal to the velocity V_c is zero.
- The angle between the direction of chip flow and the normal to the cutting edge of the tool, measured in the plane of the tool face is zero.
- The cutting edge is longer than the width of the cut.

Oblique Cutting

- The cutting edge of the tool always remains inclined at an acute angle to the direction of tool feed or work feed.
- The direction of chip flow velocity is at an angle β with the normal to the cutting edge of the tool. (*chip flow angle*)
- The cutting edge of the tool is inclined at an 'i' with the normal to the direction of work feed or tool feed V_c .
- Three mutually perpendicular components of cutting forces act at the cutting edge of the tool.
- The cutting edge may or may not be longer than the width of the cut.

CHIP FORMATION

Mechanism of chip formation

Machining is a semi-finishing or finishing process essentially done to impart required or stipulated dimensional and form accuracy and surface finish to enable the product to:

Fulfill its basic functional requirements. Provide better or improved performance. Render long service life. Machining is a process of gradual removal of excess material from the preformed blanks in the form of chips.

The form of the chips is an important index of machining because it directly or indirectly indicates:

Nature and behavior of the work material under machining condition.

Specific energy requirement (amount of energy required to remove unit volume of work material) in machining work. Nature and degree of interaction at the chip-tool interfaces.

The form of machined chips depends mainly upon:

Work material. Material and geometry of the cutting tool.

Levels of cutting velocity and feed and also to some extent on depth of cut.

Machining environment or cutting fluid that affects temperature and friction at the chip-tool and work-tool interfaces.

Mechanism of chip formation in machining ductile materials

Knowledge of basic mechanism(s) of chip formation helps to understand the characteristics of chips and to attain favorable chip forms.

During continuous machining the uncut layer of the work material just ahead of the cutting tool (edge) is subjected to almost all sided compression as indicated in Fig.10.





Fig. 10 Compression of work material (layer) ahead of the tool tip

The force exerted by the tool on the chip arises out of the normal force, N and frictional force, F as indicated in Fig. 10. Due to such compression, shear stress develops, within that compressed region, in different magnitude, in different directions and rapidly increases in magnitude. Whenever and wherever the value of the shear stress reaches or exceeds the shear strength of that work material in the deformation region, yielding or slip takes place resulting shear deformation in that region and the plane of maximum shear stress. But the forces causing the shear stresses in the region of the chip quickly diminishes and finally disappears while that region moves along the tool rake surface towards and then goes beyond the point of chip-tool engagement.

As a result the slip or shear stops propagating long before total separation takes place. In the mean time the succeeding portion of the chip starts undergoing compression followed by yielding and shear. This phenomenon repeats rapidly resulting in formation and removal of chips in thin layer by layer. This phenomenon has been explained in a simple way by Piispanen^{*1} using a card analogy as shown in Fig.11 (a).



(a) Shifting of the postcards by partial sliding against each other (b) Chip formation by shear in lamella Fig. 11 Piispanen model of card analogy to explain chip formation in machining ductile materials

In actual machining chips also, such serrations are visible at their upper surface as indicated in Fig. 11 (b). The lower surface becomes smooth due to further plastic deformation due to intensive rubbing with the tool at high pressure and temperature. The pattern of shear deformation by lamellar sliding, indicated in the model, can also be seen in actual chips by proper mounting, etching and polishing the side surface of the machining chip and observing under microscope.

The pattern and extent of total deformation of the chips due to the primary and the secondary shear deformations of the chips ahead and along the tool face, as indicated in Fig. 12, depend upon: Work material. Tool; material and geometry. The machining speed (V_C) and feed (s_o). Cutting fluid application.




Fig. 12 Primary and secondary deformation zones in the chip

The overall deformation process causing chip formation is quite complex and hence needs thorough experimental studies for clear understanding the phenomena and its dependence on the affecting parameters. The feasible and popular experimental methods^{*2} for this purpose are:

Study of deformation of rectangular or circular grids marked on side surface as shown in Fig.13 (a and b).

Microscopic study of chips frozen by drop tool or quick stop apparatus.

Study of running chips by high speed camera fitted with low magnification microscope.

It has been established by several analytical and experimental methods including circular grid deformation that though the chips are initially compressed ahead of the tool tip, the final deformation is accomplished mostly by shear in machining ductile materials. However, machining of ductile materials generally produces flat, curved or coiled continuous chips.




Fig.13 Pattern of grid deformation during chip formation (a) Rectangular grids
(b) Circular grids

Mechanism of chip formation in machining brittle materials

The basic two mechanisms involved in chip formation are:

Yielding - generally for ductile materials. Brittle fracture - generally for brittle materials.

During machining, first a small crack develops at the tool tip as shown in Fig. 14 due to wedging action of the cutting edge. At the sharp crack-tip stress concentration takes place. In case of ductile materials immediately yielding takes place at the crack-tip and reduces the effect of stress concentration and prevents its propagation as crack. But in case of brittle materials the initiated crack quickly propagates, under stressing action, and total separation takes place from the parent work piece through the minimum resistance path as indicated in Fig. 14.





Fig. 14 Development and propagation of crack causing chip separation.

Machining of brittle material produces discontinuous chips and mostly of irregular size and shape. The process of forming such chips is schematically shown in Fig. 1.15 (a, b, c, d and e).



(a) Separation (b) Swelling (c) Further swelling (d) Separation (e) Swelling again
 Fig. 15 Schematic view of chip formation in machining brittle materials

Chip thickness ratio

Geometry and characteristics of chip forms

The geometry of the chips being formed at the cutting zone follow a particular pattern especially in machining ductile materials. The major sections of the engineering materials being machined are ductile in nature; even some semi-ductile or semi-brittle materials behave ductile under the compressive forces at the cutting zone during machining.

The pattern and degree of deformation during chip formation are quantitatively assessed and expressed by some factors, the values of which indicate about the forces and energy required for a particular machining work.

Chip reduction coefficient or cutting ratio

The usual geometrical features of formation of continuous chips are schematically shown in Fig.16. The chip thickness (a_2) usually becomes larger than the uncut chip thickness (a_1). The reason can be attributed to:

Compression of the chip ahead of the tool. Frictional resistance to chip flow.

Lamellar sliding according to Piispanen.




Fig. 16 Geometrical features of continuous chip formation.

The significant geometrical parameters involved in chip formation are shown in Fig. 16 and those parameters are defined (in respect of straight turning) as:

t = depth of cut (mm) - perpendicular penetration of the cutting tool tip in work surface.

f = feed (mm/rev) - axial travel of the tool per revolution of the job.

b_1 = width (mm) of chip before cut.

b_2 = width (mm) of chip after cut.

a_1 = thickness (mm) of uncut layer (or chip before cut).

a_2 = chip thickness (mm) - thickness of chip after cut.

A_1 = cross section (area, mm²) of chip before cut.

The degree of thickening of the chip is expressed by

$$r_c = a_2 / a_1 > 1.00 \quad (\text{since } a_2 > a_1)$$

where, r_c = chip reduction coefficient.

$$a_1 = f \sin \phi$$

where ϕ = principal cutting edge angle.

Larger value of r_c means more thickening i.e., more effort in terms of forces or energy required to accomplish the machining work. Therefore it is always desirable to reduce a_2 or r_c without sacrificing productivity, i.e. metal removal rate (MRR).

The degree of thickening of the chip is expressed by

$$r_c = a_2 / a_1 > 1.00 \quad (\text{since } a_2 > a_1)$$

where, r_c = chip reduction coefficient.

$$a_1 = f \sin \phi$$

where ϕ = principal cutting edge angle.

Larger value of r_c means more thickening i.e., more effort in terms of forces or energy required to accomplish the machining work. Therefore it is always desirable to reduce a_2 or r_c without sacrificing productivity, i.e. metal removal rate (MRR).

Chip thickening is also often expressed by the reciprocal of r_c as,

$$1 / r_c = r = a_1 / a_2$$

where r = cutting ratio.

The value of chip reduction coefficient, r_c (and hence cutting ratio) depends mainly upon

→ Tool rake angle, γ → Chip-tool interaction, mainly friction, μ

Roughly in the following way,³

$$r_c = e^{\mu(\frac{\pi}{2} - \gamma)} \quad (\text{for orthogonal cutting})$$

$\frac{\pi}{2}$ and γ are in radians.

The simple but very significant expression 1.4 clearly depicts that the value of r_c can be desirably reduced by

- Using tool having larger positive rake.
- Reducing friction by using lubricant.

The role of rake angle and friction at the chip-tool interface on chip reduction coefficient are also schematically shown in Fig. 17.




Fig. 17 Role of rake angle and friction on chip reduction coefficient




Fig. 18 Shear plane and shear angle in chip formation

Chip reduction coefficient, r_c is generally assessed and expressed by the ratio of the chip thickness, after cut (a_2) and before cut (a_1) as in equation 1.1. But r_c can also be expressed or assessed by the ratio of:

Total length of the chip before cut (L_1) and after cut (L_2).

Cutting velocity, V_C and chip velocity, V_f .

Considering total volume of chip produced in a given time,

$$a_1 b_1 L_1 = a_2 b_2 L_2$$

The width of chip, b generally does not change significantly during machining unless there is side flow for some adverse situation. Therefore assuming, $b_1=b_2$, r_c comes up to be,

$$r_c = a_2 / a_1 = L_1 / L_2$$

Again considering unchanged material flow (volume) ratio, Q

$$Q = (a_1 b_1) V_C = (a_2 b_2) V_f$$

Taking $b_1=b_2$,

$$r_c = a_2 / a_1 = V_C / V_f$$

Equation reveals that the chip velocity, V_f will be lesser than the cutting velocity, V_C and the ratio is equal

to the cutting ratio, $r = 1 / r_c$

Shear plane

Shear plane is the plane of separation of work material layer in the form of chip from the parent body due to shear along that plane.

Shear angle

It has been observed that during machining, particularly ductile materials, the chip sharply changes its direction of flow (relative to the tool) from the direction of the cutting velocity, V_C to that along the tool rake surface after thickening by shear deformation or slip or lamellar sliding along a plane.

This plane is called shear plane and is schematically shown in Fig. 18.

Angle of inclination of the shear plane from the direction of cutting velocity as shown in Fig. 18.

The value of shear angle, denoted by β (taken in orthogonal plane) depends upon:

Chip thickness before cut and after cut i.e. r_c . Rake angle, γ (in orthogonal plane).

From Fig. 18,

$$AC = a_2 = OA \cos(\beta - \gamma) \text{ and } AB = a_1 = OA \sin\beta \quad \text{dividing } a_2 \text{ by } a_1$$

$$a_2 / a_1 = r_c = \cos(\beta - \gamma) / \sin\beta$$

$$\text{or } \tan\beta = \cos\gamma / r_c - \sin\gamma$$

Replacing chip reduction coefficient, r_c by cutting ratio, r , the above equation changes to,

$$\tan\beta = r \cos\gamma / 1 - r \sin\gamma$$

Equation depicts that with the increase in r_c , shear angle decreases and vice-versa. It is also evident from equation, that shear angle increases both directly and indirectly with the increase in tool rake angle. Increase in shear angle means more favorable machining condition requiring lesser specific energy.

Cutting strain

The magnitude of strain, that develops along the shear plane due to machining action, is called cutting strain (shear). The relationship of this cutting strain, ϵ with the governing parameters can be derived from Fig. 19.




Fig. 19 Cutting strain in machining

Due to presence of the tool as an obstruction the layer 1 has been shifted to position 2 by sliding along the shear plane. From Fig.

Cutting strain (average), $\epsilon = s / Y = PM / ON$

or $\epsilon = PN + NM / ON$

$\epsilon = PN / ON + NM / ON$

or $\epsilon = \cot \beta + \tan(\beta - \gamma)$

Built-up-Edge (BUE) formation

Causes of formation

In machining ductile metals like steels with long chip-tool contact length, lot of stress and temperature develops in the secondary deformation zone at the chip-tool interface. Under such high stress and temperature in between two clean surfaces of metals, strong bonding may locally take place due to adhesion similar to welding. Such bonding will be encouraged and accelerated if the chip tool materials have mutual affinity or solubility.

The weldment starts forming as an embryo at the most favorable location and thus gradually grows as schematically shown in Fig.20




Fig. 20. Scheme of built-up-edge formation

With the growth of the BUE, the force, F (shown in Fig. 1.20) also gradually increases due to wedging action of the tool tip along with the BUE formed on it. Whenever the force, F exceeds the bonding force of the BUE, the BUE is broken or sheared off and taken away by the flowing chip. Then again BUE starts forming and growing. This goes on repeatedly.

Characteristics of BUE

Built-up-edges are characterized by its shape, size and bond strength, which depend upon:

Work tool materials.

Stress and temperature, i.e., cutting velocity and feed.

Cutting fluid application governing cooling and lubrication.

BUE may develop basically in three different shapes as schematically shown in Fig. (a, b and c).




Fig. 21. Different forms of built-up-edge.




Fig.22.Overgrowing and overflowing of BUE causing surface roughness

In machining too soft and ductile metals by tools like high speed steel or uncoated carbide the BUE may grow larger and overflow towards the finished surface through the flank as shown in Fig. 22. While the major part of the detached BUE goes away along the flowing chip, a small part of the BUE may remain stuck on the machined surface and spoils the surface finish. BUE formation needs certain level of temperature at the interface depending upon the mutual affinity of the work-tool materials. With the increase in V_C and so the cutting temperature rises and favors BUE formation. But if V_C is raised too high beyond certain limit, BUE will be squashed out by the flowing chip before the BUE grows.

Effects of BUE formation

Formation of BUE causes several harmful effects, such as:

It unfavorably changes the rake angle at the tool tip causing increase in cutting forces and power consumption.

Repeated formation and dislodgement of the BUE causes fluctuation in cutting forces and thus induces vibration which is harmful for the tool, job and the machine tool.

Surface finish gets deteriorated.

May reduce tool life by accelerating tool-wear at its rake surface by adhesion and flaking occasionally, formation of thin flat type stable BUE may reduce tool wear at the rake face.

Types of chips

Different types of chips of various shape, size, colour etc. are produced by machining depending upon:

Type of cut, i.e., continuous (turning, boring etc.) or intermittent cut (milling). Work material (brittle or ductile etc.).

Cutting tool geometry (rake, cutting angles etc.).

Levels of the cutting velocity and feed (low, medium or high). Cutting fluid (type of fluid and method of application).

The basic major types of chips and the conditions generally under which such types of chips form are given below:

Continuous chips without BUE

When the cutting tool moves towards the work piece, there occurs a plastic deformation of the work piece and the metal is separated without any discontinuity and it moves like a ribbon. The chip moves along the face of the tool. This mostly occurs while cutting a ductile material. It is desirable to have smaller chip thickness and higher cutting speed in order to get continuous chips. Lesser power is consumed while continuous chips are produced. Total life is also mortised in this process. The formation of continuous chips is schematically shown in Fig. 23.




Fig. 23 Formation of continuous chips




Fig. 24 Formation of discontinuous chips

The following condition favors the formation of continuous chips without BUE chips:

Work material - ductile. Cutting velocity - high. Feed - low.

Rake angle - positive and large. Cutting fluid - both cooling and lubricating.

Discontinuous chips

This is also called as segmental chips. This mostly occurs while cutting brittle material such as cast iron or low ductile materials. Instead of shearing the metal as it happens in the previous process, the metal is being fractured like segments of fragments and they pass over the tool faces. Tool life can also be more in this process. Power consumption as in the previous case is also low. The formation of continuous chips is schematically shown in Fig. 24.

The following condition favors the formation of discontinuous chips:

Of irregular size and shape: - work material - brittle like grey cast iron.

Of regular size and shape: - work material ductile but hard and work hardenable. Feed rate - large.

Tool rake - negative. Cutting fluid - absent or inadequate.

Continuous chips with BUE

When cutting a ductile metal, the compression of the metal is followed by the high heat at tool face. This in turns enables part of the removed metal to be welded into the tool. This is known as built up edge, a very hardened layer of work material attached to the tool face, which tends to act as a cutting edge itself replacing the real cutting tool edge.

The built-up edge tends to grow until it reaches a critical size (~ 0.3 mm) and then passes off with the chip, leaving small fragments on the machining surface. Chip will break free and cutting forces are smaller, but the effect is a rough machined surface. The built-up edge disappears at high cutting speeds.

The weld metal is work hardened or strain hardened. While the cutting process is continued, some of built up edge may be combined with the chip and pass along the tool face. Some of the built up edge may be permanently fixed on the tool face. This produces a rough surface finish and the tool life may be reduced. The formation of continuous chips with BUE is schematically shown in Fig. 25.




Fig. 25 Formation of continuous chips with BUE

The following condition favors the formation of continuous chips with BUE chips:

Work material - ductile.

Cutting velocity - low (~ 0.5 m/s.). Small or negative rake angles.

Feed - medium or large.

Cutting fluid - inadequate or absent.

Often in machining ductile metals at high speed, the chips are deliberately broken into small segments of regular size and shape by using chip breakers mainly for convenience and reduction of chip-tool contact length.

Chip breakers

Need and purpose of chip-breaking

Continuous machining like turning of ductile metals, unlike brittle metals like grey cast iron, produce continuous chips, which leads to their handling and disposal problems. The problems become acute when ductile but strong metals like steels are machined at high cutting velocity for high MRR by flat rake face type carbide or ceramic inserts.

The sharp edged hot continuous chip that comes out at very high speed:

Becomes dangerous to the operator and the other people working in the vicinity. May impair the finished surface by entangling with the rotating job.

Creates difficulties in chip disposal.

Therefore it is essentially needed to break such continuous chips into small regular pieces for:

Safety of the working people.

Prevention of damage of the product. Easy collection and disposal of chips.

Chip breaking is done in proper way also for the additional purpose of improving machinability by reducing the chip-tool contact area, cutting forces and crater wear of the cutting tool.

Principles of chip-breaking

In respect of convenience and safety, closed coil type chips of short length and 'coma' shaped broken-to-half turn chips are ideal in machining of ductile metals and alloys at high speed.

The principles and methods of chip breaking are generally classified as follows:

Self chip breaking - This is accomplished without using a separate chip-breaker either as an attachment or an additional geometrical modification of the tool.


Forced chip breaking - This is accomplished by additional tool geometrical features or devices.

a) Self breaking of chips

Ductile chips usually become curled or tend to curl (like clock spring) even in machining by tools with flat rake surface due to unequal speed of flow of the chip at its free and generated (rubbed) surfaces and unequal temperature and cooling rate at those two surfaces. With the increase in cutting velocity and rake angle (positive) the radius of curvature increases, which is more dangerous.

In case of oblique cutting due to presence of inclination angle, restricted cutting effect etc. the curled chips deviate laterally resulting helical coiling of the chips. The curled chips may self break:

By natural fracturing of the strain hardened outgoing chip after sufficient cooling and spring back as indicated in Fig. 27 (a). This kind of chip breaking is generally observed under the condition close to that which favors formation of jointed or segmented chips. By striking against the cutting surface of the job, as shown in Fig.276 (b), mostly under pure orthogonal cutting. By striking against the tool flank after each half to full turn as indicated in Fig. 27 (c).



(a) Natural (b) Striking on job (c) Striking at tool flank

Fig. 26 Principles of self breaking of chips

The possibility and pattern of self chip-breaking depend upon the work material, tool material and tool geometry (γ , λ , ϕ and r), levels of the process parameters (V_C and f_o) and the machining environment (cutting fluid application) which are generally selected keeping in view the overall machinability.

b) Forced chip-breaking

The hot continuous chip becomes hard and brittle at a distance from its origin due to work hardening and cooling. If the running chip does not become enough curled and work hardened, it may not break. In that case the running chip is forced to bend or closely curl so that it breaks into pieces at regular intervals. Such broken chips are of regular size and shape depending upon the configuration of the chip breaker. Chip breakers are basically of two types:

- (1) In-built type.
- (2) Clamped or attachment type.


In-built breakers are in the form of step or groove at the rake surface near the cutting edges of the tools.

Such chip breakers are provided either:

After their manufacture - in case of HSS tools like drills, milling cutters, broaches etc and brazed type carbide inserts.

During their manufacture by powder metallurgical process - e.g., throw away type inserts of carbides, ceramics and cermets.

The basic principle of forced chip breaking is schematically shown in Fig. 27. When the strain hardened and brittle running chip strikes the heel, the cantilever chip gets forcibly bent and then breaks.



$W =$ width, $H =$ height, $\beta =$ shear angle Fig. 27. Principle of forced chip breaking

Fig. 1.29 (a, b, c and d) schematically shows some commonly used step type chip breakers:

Parallel step.

Angular step; positive and negative type.

Parallel step with nose radius - for heavy cuts.





Fig. 28. Step type in-built chip breaker (a) Parallel step
(b) Parallel and radiused (c) Positive angular (d) Negative angular

Fig. 29 (a and b) schematically shows some commonly used groove type in-built chip breakers:

Circular groove. Tilted Vee groove.



(a) Circular groove (b) Tilted Vee groove
Fig. 29 Groove type in-built chip breaker

The unique characteristics of in-built chip breakers are:

The outer end of the step or groove acts as the heel that forcibly bends and fractures the running chip.

Simple in configuration, easy manufacture and inexpensive.

The geometry of the chip-breaking features is fixed once made. (i.e., cannot be controlled) Effective only for fixed range of speed and feed for any given tool-work combination.

(c) Clamped type chip-breaker


Clamped type chip breakers work basically in the principle of stepped type chip-breaker but have the provision of varying the width of the step and / or the angle of the heel.

Fig. 30 (a, b and c) schematically shows three such chip breakers of common use:

With fixed distance and angle of the additional strip - effective only for a limited domain of parametric combination.

With variable width (W) only - little versatile.

With variable width (W), height (H) and angle (β) - quite versatile but less rugged and more expensive.



(a) Fixed geometry (b) Variable width (c) Variable width and angle

Fig. 1.30 Clamped type chip breakers

(d) Chip breakers in solid HSS tools

Despite advent of several modern cutting tool materials, HSS is still used for its excellent TRS (transverse rupture strength) and toughness, formability, grindability and low cost. The cutting tools made of solid HSS blanks, such as form tools, twist drills, slab milling cutters, broaches etc, are also often used with suitable chip breakers for breaking the long or wide continuous chips.

The handling of wide and long chips often becomes difficult particularly while drilling large diameter and deep holes. Grooves, either on the rake faces or on the flanks as shown in Fig. 31 help to break the chips both along the length and breadth in drilling ductile metals. The locations of the grooves are offset in the two cutting edges.




Fig. 31 Chip breaking grooves.

(b) US industrial design of chip-breaking drill

(a) Crisp design of chip-breaking drill

Plain milling and end milling inherently produces discontinuous ‘coma’ shaped chips of favorably shorter length. But the chips become very wide while milling wide surfaces and may offer problem of chip disposal. To reduce this problem, the milling cutters are provided with small peripheral grooves on the cutting edges as shown in Fig. 32. Such in-built type chip breakers break the wide chips into a number of chips of much shorter width. Similar groove type chip-breakers are also often provided along the teeth of broaches, for breaking the chips to shorter width and ease of disposal.




Fig. 32 Chip breaking grooves on a plain helical milling cutter

(e) Dynamic chip breaker

Dynamic turning is a special technique, where the cutting tool is deliberately vibrated along the direction of feed as indicated in Fig. 1.35 at suitable frequency and amplitude. Such additional controlled tool oscillation caused by mechanical, hydraulic or electro-magnetic (solenoid) shaker improves surface finish. This also reduces the cutting forces and enhances the tool life due to more effective cooling and lubrication at the chip tool and work tool interfaces for intermittent break of the tool-work contact. Such technique, if further slightly adjusted, can also help breaking the chips. When the two surfaces of the chip will be waved by phase difference of about 90^0 , the chip will either break immediately or will come out in the form of bids, which will also break with slight bending or pressure as indicated in Fig. 1.35. This technique of chip breaking can also be accomplished in dynamic drilling and dynamic boring. Fig. 1.36 schematically shows another possible dynamic chip-breaking device suitable for radially fed type lathe operations, e.g., facing, grooving and parting.




Fig 33 Self chip breaking in dynamic turning




Fig 34 Dynamic chip breaking in radial operations in lathe

Overall effects of chip breaking

Favorable effects:

- Safety of the operator(s) from the hot, sharp continuous chip flowing out at high speed.
- Convenience of collection and disposal of chips.
- A chance of damage of the finished surface by entangling or rubbing with the chip is eliminated.
- More effective cutting fluid action due to shorter and varying chip tool contact length.

Unfavorable effects:

Chances of harmful vibration due to frequent chip breaking and hitting at the heel or flank of the tool bit.

More heat and stress concentration near the sharp cutting edge and hence chances of its rapid failure.

Surface finish may deteriorate.

ORTHOGONAL METAL CUTTING

Benefit of knowing and purpose of determining cutting forces

The aspects of the cutting forces concerned:

Magnitude of the cutting forces and their components. Directions and locations of action of those forces.

Pattern of the forces: static and / or dynamic.

Knowing or determination of the cutting forces facilitate or are required for:

Estimation of cutting power consumption, which also enables selection of the power source(s) during design of the machine tools.

Structural design of the machine - fixture - tool system.

Evaluation of role of the various machining parameters (process - V_C , f_0 , t , tool - material and geometry, environment - cutting fluid) on cutting forces.

Study of behaviour and machinability characterization of the work materials. Condition monitoring of the cutting tools and machine tools.

Cutting force components and their significances

The single point cutting tools being used for turning, shaping, planing, slotting, boring etc. are characterized by having only one cutting force during machining. But that force is resolved into two or three components for ease of analysis and exploitation. Fig. 1.37 visualizes how the single cutting force in turning is resolved into three components along the three orthogonal directions; X, Y and Z.

The resolution of the force components in turning can be more conveniently understood from their display in 2-D as shown in Fig. 1.38.




Fig. 35 Cutting force R resolved into P_X , P_Y and P_Z




Fig.36 turning force resolved into P_Z , P_X and P_Y

The resultant cutting force, R is resolved as,

$$R = P_Z + P_{XY} \tag{1.13}$$

$$\text{And } P_{XY} = P_X + P_Y \tag{1.14}$$

$$\text{where, } P_X = P_{XY} \sin\phi \tag{1.15}$$

$$\text{And } P_Y = P_{XY} \cos\phi \tag{1.16}$$

P_Z - Tangential component taken in the direction of Z_m axis.

P_X - Axial component taken in the direction of longitudinal feed or X_m axis. P_Y - Radial or transverse component taken along Y_m axis.

In Fig. 1.37 and Fig. 1.38 the force components are shown to be acting on the tool. A similar set of forces also act on the job at the cutting point but in opposite directions as indicated by P_Z' , P_{XY}' , P_X' and P_Y' in Fig. 1.38.

Significance of P_Z , P_X and P_Y

P_Z : Called the main or major component as it is the largest in magnitude. It is also called power component as it being acting along and being multiplied by V_C decides cutting power ($P_Z \cdot V_C$) consumption. P_Y : May not be that large in magnitude but is responsible for causing dimensional inaccuracy and vibration.

P_X : It, even if larger than P_Y , is least harmful and hence least significant.

Merchant's Circle Diagram and its use

In orthogonal cutting when the chip flows along the orthogonal plane, π_0 , the cutting force (resultant) and its components P_Z and P_{XY} remain in the orthogonal plane. Fig. 37 is schematically showing the forces acting on a piece of continuous chip coming out from the shear zone at a constant speed. That chip is apparently in a state of equilibrium.




Fig 37 Development of Merchant's circle diagram




Fig.38 Merchant's Circle Diagram with cutting forces

The forces in the chip segment are:

From job-side: P_s - Shear force. P_n - force normal to the shear force

From the tool side: $R_1 = R$ (in state of equilibrium) where, $R_1 = F + N$

N - Force normal to rake face. F - Friction force at chip tool interface.

The resulting cutting force R or R_1 can be resolved further as,

$R_1 = P_Z + P_{XY}$ where, P_Z - Force along the velocity vector. P_{XY} - force along orthogonal plane.

The circle(s) drawn taking R or R_1 as diameter is called Merchant's circle which contains all the force components concerned as intercepts. The two circles with their forces are combined into one circle having all the forces contained in that as shown by the diagram called Merchant's Circle Diagram (MCD) in Fig. 38. The significance of the forces displayed in the Merchant's Circle Diagram is:

P_s - The shear force essentially required to produce or separate the chip from the parent body by shear.

P_n - Inherently exists along with P_s . F - Friction force at the chip tool interface. N - Force acting normal to the rake surface.

$P_Z = P_{XY} - P_X + P_Y =$ main force or power component acting in the direction of cutting velocity.

The magnitude of P_s provides the yield shear strength of the work material under the cutting action. The values of F and the ratio of F and N indicate the nature and degree of interaction like friction at the chip tool interface.

The force components P_X , P_Y , P_Z are generally obtained by direct measurement. Again P_Z helps in determining cutting power and specific energy requirement. The force components are also required to design the cutting tool and the machine tool.

Advantageous use of Merchant's circle diagram

Proper use of MCD enables the followings:

Easy, quick and reasonably accurate determination of several other forces from a few known forces involved in machining.

Friction at chip tool interface and dynamic yield shear strength can be easily determined. Equations relating the different forces are easily developed.

Some limitations of use of MCD:

Merchant's circle diagram (MCD) is only valid for orthogonal cutting.

By the ratio, F/N , the MCD gives apparent (not actual) coefficient of friction. It is based on single shear plane theory.

Development of equations for estimation of cutting forces

The two basic methods of determination of cutting forces and their characteristics are:

(a) Analytical method: Enables estimation of cutting forces.

Characteristics:

Easy, quick and inexpensive. Very approximate and average.

Effect of several factors like cutting velocity, cutting fluid action etc. are not revealed. Unable to depict the dynamic characteristics of the forces.

(b) Experimental methods: Direct measurement.

Characteristics:

Quite accurate and provides true picture.

Can reveal effect of variation of any parameter on the forces. Depicts both static and dynamic parts of the forces.

Needs measuring facilities, expertise and hence expensive.

The equations for analytical estimation of the salient cutting force components are conveniently developed using Merchant's Circle Diagram (MCD) when it is orthogonal cutting by any single point cutting tool like, in turning, shaping, planing, boring etc.

Development of mathematical expressions for cutting forces

Tangential or main component, P_Z

This can be very conveniently done by using Merchant's Circle Diagram, as shown in Fig. 1.40.

From the MCD shown in Fig. 1.40,

$$P_Z = R \cos(\eta - \gamma) \quad 1.17$$

$$P_S = R \cos(\beta + \eta - \gamma) \quad 1.18$$

Dividing Eqn. 1.17 by Eqn. 1.18,

$$P_Z = P_S \cos(\eta - \gamma) / \cos(\beta + \eta - \gamma) \quad 1.19$$

$$\text{It was already shown that, } P_S = \text{t.f. } \tau_s / \sin\beta \quad 1.20$$

where, τ_s - Dynamic yield shear strength of the work material.

$$P_Z = \text{t.f. } \tau_s \cos(\eta - \gamma) / \sin\beta \cos(\beta + \eta - \gamma) \quad 1.21$$

Thus,

For brittle work materials, like grey cast iron, usually,

$2\beta + \eta - \gamma = 90^\circ$ and τ_s remains almost unchanged.

Then for turning brittle material,

$$P_Z = \text{t.f. } \tau_s \cos(90^\circ - 2\beta) / \sin\beta \cos(90^\circ - \beta) \quad 1.22$$

$$P_Z = 2 \text{ t.f. } \tau_s \cot\beta \quad 1.23$$

Where, $\cot\beta = r_c - \tan\gamma$

$$r_c = a_2 / a_1 = a_2 / f \sin\phi$$

or

It is difficult to measure chip thickness and evaluate the values of ζ while machining brittle materials and the value of τ_s is roughly estimated from

$$\tau_s = 0.175 \text{ BHN} \quad 1.24$$

where, BHN - Brinell's Hardness number.

But most of the engineering materials are ductile in nature and even some semi-brittle materials behave ductile under the cutting condition. The angle relationship reasonably accurately applicable for

ductile metals is

$$\beta + \eta - \gamma = 45^0 \quad 1.25$$

and the value of τ_s is obtained from,

$$\tau_s = 0.186 \text{ BHN (approximate)} \quad 1.26$$

$$\text{or } \tau_s = 0.74\sigma_u \varepsilon^{0.6} \text{ (more suitable and accurate)} \quad 1.27$$

where, σ_u - Ultimate tensile strength of the work material

$$\varepsilon - \text{Cutting strain, } \varepsilon \cong r_c - \tan \gamma$$

- % elongation

Substituting Eqn. 1.25 in Eqn. 1.21,

$$P_Z = \text{t.f. } \tau_s (\cot \beta + 1) \quad 1.28$$

Again $\cot \beta \cong r_c - \tan \gamma$

$$\text{So, } P_Z = \text{t.f. } \tau_s (r_c - \tan \gamma + 1) \quad 1.29$$

Axial force, P_X and transverse force, P_Y

From the MCD shown in Fig. 1.40,

$$P_{XY} = P_Z \tan(\eta - \gamma) \quad 1.30$$

Combining Eqn. 1.21 and Eqn. 1.30,

$$P_{XY} = \text{t.f. } \tau_s \sin(\eta - \gamma) / \sin \beta \cos(\beta + \eta - \gamma) \quad 1.31$$

Again, using the angle relationship

$$\beta + \eta - \gamma = 45^0, \text{ for ductile material}$$

$$P_{XY} = \text{t.f. } \tau_s (\cot \beta - 1) \quad 1.32$$

$$\text{or } P_{XY} = \text{t.f. } \tau_s (r_c - \tan \gamma - 1) \quad 1.33$$

$$\text{where, } \tau_s = 0.74\sigma_u \varepsilon^{0.6} \text{ or } \tau_s = 0.186 \text{ BHN}$$

It is already known,

$$P_X = P_{XY} \sin \phi \quad \text{and} \quad P_Y = P_{XY} \cos \phi$$

$$\text{Therefore, } P_X = \text{t.f. } \tau_s (r_c - \tan \gamma - 1) \sin \phi \quad 1.34$$

$$\text{and } P_Y = \text{t.f. } \tau_s (r_c - \tan \gamma - 1) \cos \phi \quad 1.35$$

Friction force, F , normal force, N and apparent coefficient of friction μ_a

From the MCD shown in Fig. 1.40,

$$F = P_Z \sin \gamma + P_{XY} \cos \gamma \quad 1.36$$

$$\text{and } N = P_Z \cos \gamma - P_{XY} \sin \gamma \quad 1.37$$

$$\mu_a = F / N = P_Z \sin \gamma + P_{XY} \cos \gamma / P_Z \cos \gamma - P_{XY} \sin \gamma \quad 1.38$$

$$\text{or } \mu_a = P_Z \tan \gamma + P_{XY} / P_Z - P_{XY} \tan \gamma \quad 1.39$$

Therefore, if P_Z and P_{XY} are known or determined either analytically or experimentally the values of F , N and μ_a can be determined using equations only.

Shear force P_s and P_n

From the MCD shown in Fig. 1.40,

$$P_s = P_Z \cos \beta - P_{XY} \sin \beta \quad 1.40$$

$$\text{And } P_n = P_Z \sin \beta + P_{XY} \cos \beta \quad 1.41$$

From P_s , the dynamic yield shear strength of the work material, τ_s can be determined by using the relation,

$$P_s = A_s \tau_s$$

where, $A_s = t.f / \sin\beta =$ Shear area

Therefore

$$\tau_s = P_s \sin\beta / t.f$$

$$\tau_s = (P_Z \cos\beta - P_{XY} \sin\beta) \sin\beta / t.f \quad 1.42$$

Metal cutting theories

Earnst - Merchant theory

Earnst and Merchant have developed a relationship between the shear angle β , the cutting rake angle γ , and the angle of friction η as follows:

$2\beta + \eta - \gamma = C$ where C is a machining constant for the work material dependent on the rate of change of the shear strength of the metal with applied compressive stress, besides taking the internal coefficient of friction into account.

Modified - Merchant theory

According to this theory the relation between the shear angle β , the cutting rake angle γ , and the angle of friction η as follows:

$$\beta = \frac{\pi}{4} - \frac{\eta}{2} + \frac{\gamma}{2}$$

Shear will take place in a direction in which energy required for shearing is minimum. Shear stress is maximum at the shear plane and it remains constant.

Lee and Shaffer's theory

This theory analysis the process of orthogonal metal cutting by applying the theory of plasticity for an ideal rigid plastic material. The principle assumptions are:

The work piece material ahead of the cutting tool behaves like an ideal plastic material. The deformation of the metal occurs on a single shear plane.

This is a stress field within the produced chip which transmits the cutting force from the shear plane to the tool face and therefore, the chip does not get hardened.

The chip separates from the parent material at the shear plane.

Based on this, they developed a slip line field for stress zone, in which no deformation would occur even if it is stressed to its yield point. From this, they derived the following relationship.

$$\beta = \frac{\pi}{4} - \eta + \gamma$$

Velocity relationship

The velocity relationships for orthogonal cutting are illustrated in fig. 2.7 where V_C is the cutting velocity, V_s is the velocity of shear and V_f is the velocity of chip flow up the tool face.

$$V_s = V_C \cos\gamma / \cos(\beta - \gamma) \quad 1.43$$

$$\text{and } V_f = \sin\beta / \cos(\beta - \gamma) \quad 1.44$$


$$\text{From equation } V_f = V_C / r_c$$

It can be inferred from the principle of kinematics that the relative velocity of two bodies (here tool and the chip) is equal to the vector difference between their velocities relative to the reference body (the workpiece). So, $V_C = V_s + V_f$ 1.45

TEMPERATURE MEASUREMENT

During metal cutting, heat is generated in three regions as shown in Fig.

1. Around shear plane
2. Tool-chip interface
3. Tool-work piece interface



It is the region in which actual plastic deformation of the metal occurs during machining. Due to this deformation heat is generated. A portion of this heat is carried away by the chip, due to which its temperature is raised. The rest of the heat is retained by the work piece. It is known as *Primary Deformation Zone*

Tool-chip interface

As the chip slides upwards along face of the tool friction occurs between their surfaces, due to which heat is generated. A part of this heat carried by the chip, which further raises the temperature of the chip. And the rest transferred to the tool and the coolant.

This area is secondary deformation zone. The amount of heat generated due to friction increases with the increase in cutting speed. It is not appreciably effected with the increase in depth of cut. When the feed rate is increased the amount of frictional heat generated is relatively low. But, in that case, The surface finish obtained is inferior.


The feasible experimental methods are:

- » Calorimetric method - quite simple and low cost but inaccurate and gives only grand average value
- » Decolorizing agent - some paint or tape, which change in color with variation of temperature, is pasted on the tool or job near the cutting point; the as such color of the chip (steels) may also often indicate cutting temperature
- » Tool-work thermocouple - simple and inexpensive but gives only average or maximum value.
- » Moving thermocouple technique
- » Embedded thermocouple technique
- » Using compound tool
- » Indirectly from Hardness and structural transformation
- » Photo-cell technique
- » Infra ray detection method

Tool work thermocouple technique

Principle: In a thermocouple two dissimilar but electrically conductive metals are connected at two junctions.- Whenever one of the junctions is heated, the difference in temperature at the hot and cold junctions produce proportional current which is detected and measured by a millivoltmeter.

In machining like turning, the tool and the job constitute the two dissimilar metals and the cutting zone functions as the hot junction. Then the average cutting temperature is evaluated from the mV after thorough calibration for establishing the exact relation between mV and the cutting temperature. Figure shows a method of calibration for measuring average cutting temperature, S_{avg} , in turning steel rod by uncoated carbide tool.




Moving thermocouple technique

Principle : This simple method, schematically shown in Fig. enables measure the gradual variation in the temperature of the flowing chip before, during and immediately after its formation. A bead of standard thermocouple like chrome alumel is brazed on the side surface of the layer to be removed from the work surface and the temperature is attained in terms of mV.

Embedded thermocouple technique

In operations like milling, grinding etc. where the previous methods are not applicable, embedded thermocouple can serve the purpose.

PRINCIPLE: The standard thermocouple monitors the job temperature at a certain depth, h_i from the cutting zone. The temperature recorded in oscilloscope or strip chart recorder becomes maximum when the thermocouple bead comes nearest (Slightly offset) to the grinding zone. With the progress of grinding the depth, h_i gradually decreases after each grinding pass and the value of temperature, θ_m also rises as has been indicated in Fig. For getting the temperature exactly at the surface i.e., grinding zone, h_i has to be zero, which is not possible. So the θ_m vs h_i curve has to be extrapolated up to $h_i = 0$ to get the actual grinding zone temperature. Log -log plot helps such extrapolation more easily and accurately.



Measurement of chip-tool interface temperature by compound tool

In this method a conducting tool piece (carbide) is embedded in a non conducting tool (ceramic). The conducting piece and the job form the tool-work thermocouple as shown in Fig. which detects temperature θ_1 at the location (U) of the carbide strip. Thus θ_i can be measured along the entire chip-tool contact length by gradually reducing L_i by grinding the tool flank. Before that calibration has to be done as usual.





Photo-cell technique

This unique technique enables accurate measurement of the temperature along the shear zone and tool flank as can be seen in Fig. The electrical resistance of the cell, like PbS cell, changes when it is exposed to any heat radiation. The amount of change in the resistance depends upon the temperature of the heat radiating source and is measured in terms of voltage, which is calibrated with the source temperature. The cell starts receiving radiation through the small hole only when it enters the shear zone where the hole at the upper end faces a hot surface. Receiving radiation and measurement of temperature continues until the hole passes through the entire shear zone and then the tool flank.

Infra-red photographic technique

This modern and powerful method is based on taking infra-red photograph of the hot surfaces of the tool, chip, and/or job and get temperature distribution at those surfaces. Proper calibration is to be done before that. This way the temperature profiles can be recorded in PC as indicated in Fig. The fringe pattern readily changes with the change in any machining parameter which affect cutting temperature.



Metal removal rate

It is defined as the volume of metal removed in unit time. It is used to calculate the time required to remove specified quantity of material from the work piece.

$$\text{Metal removal rate (MRR)} = t \cdot f \cdot V_C$$

where, t - Depth of cut (mm), f - Feed (mm / rev) and V_C - Cutting speed (mm / sec).

If the MRR is optimum, we can reduce the machining cost. To achieve this:

The cutting tool material should be proper. Cutting tool should be properly ground.

Tool should be supported rigidly and therefore, there should be any vibration.

$$\text{For turning operation, } \text{MRR} = t \cdot f \cdot V_C$$

$$\text{For facing and spot milling operation, } \text{MRR} = B \cdot t \cdot T$$

where B - Width of cut (mm) and T - Table travel (mm / sec).

$$\text{For planing and shaping, } \text{MRR} = t \cdot f \cdot L \cdot S$$

where L - length of workpiece (mm) and S - Strokes per minute.

Evaluation of cutting power consumption and specific energy requirement

Cutting power consumption is a quite important issue and it should always be tried to be reduced but without sacrificing MRR.

Cutting power consumption (P_C) can be determined from, $P_C = P_Z \cdot V_C + P_X \cdot V_f$

where, V_f = feed velocity = $Nf / 1000$ m/min [N = rpm]

Since both P_X and V_f , specially V_f are very small, $P_X \cdot V_f$ can be neglected and then $P_C \cong P_Z \cdot V_C$

Specific energy requirement (U_s) which means amount of energy required to remove unit volume of material, is an important machinability characteristics of the work material. Specific energy requirement, U_s , which should be tried to be reduced as far as possible, depends not only on the work material but also the process of the machining, such as turning, drilling, grinding etc. and the machining condition, i.e., V_C , f , tool material and geometry and cutting fluid application.

Compared to turning, drilling requires higher specific energy for the same work-tool materials and grinding requires very large amount of specific energy for adverse cutting edge geometry (large negative rake). Specific energy, U_s , is determined from,

$$U_s = P_Z \cdot V_C / \text{MRR} = P_Z / t \cdot f$$

CUTTING TOOL MATERIALS

Expected properties of cutting tool materials

High mechanical strength; compressive, tensile, and TRA. Fracture toughness - high or at least adequate. High hardness for abrasion resistance. High hot hardness to resist plastic deformation and reduce wear rate at elevated temperature. Chemical stability or inertness against work material, atmospheric gases and cutting fluids. Resistance to adhesion and diffusion.

Thermal conductivity - low at the surface to resist incoming of heat and high at the core to quickly dissipate the heat entered. High heat resistance and stiffness.

Manufacturability, availability and low cost.

Needs and chronological development of cutting tool materials

To meet the growing demands for high productivity, quality and economy of machining.

To enable effective and efficient machining of the exotic materials those are coming up with the rapid and vast progress of science and technology.

For precision and ultra-precision machining.

For micro and even nano machining demanded by the day and future.

Performance of the cutting tools depend upon:

The cutting tool materials.

The cutting tool geometry.

Proper selection and use of those tools.

The machining conditions and the environments.

Characteristics and applications of cutting tool materials

a) High Speed Steel (HSS)

The basic composition of HSS is 18% W, 4% Cr, 1% V, 0.7% C and rest Fe. Such HSS tool could machine (turn) mild steel jobs at speed only up to 20 ~ 30 m/min.

However, HSS is still used as cutting tool material where:

The tool geometry and mechanics of chip formation are complex, such as helical twist drills, reamers, gear shaping cutters, hobs, form tools, broaches etc.

Brittle tools like carbides, ceramics etc. are not suitable under shock loading. The small scale industries cannot afford costlier tools.

b) Stellite

This is a cast alloy of Co (40 to 50%), Cr (27 to 32%), W (14 to 19%) and C (2%). Stellite is quite tough and more heat and wear resistive than the basic HSS (18 - 4 - 1) But such stellite as cutting tool material became obsolete for its poor grindability and especially after the arrival of cemented carbides.

c) Sintered Tungsten carbides

The advent of sintered carbides made another breakthrough in the history of cutting tool materials.

- i) Straight or single carbide
- ii) Composite carbides
- iii) Mixed carbides

d) Plain ceramics

Inherently high compressive strength, chemical stability and hot hardness of the ceramics led to powder metallurgical production of indexable ceramic tool inserts since 1950. Alumina (Al_2O_3) is preferred to silicon nitride (Si_3N_4) for higher hardness and chemical stability. Si_3N_4 is tougher but again more difficult to process. The plain ceramic tools are brittle in nature and hence had limited applications.

Development and applications of advanced tool materials

- a) Coated carbides
- b) Cermets
- c) Coronite
- d) High Performance ceramics (HPC)

Nitride based ceramic tools

- i) Plain nitride ceramics tools
- ii) SIALON tools
- iii) SiC reinforced Nitride tools
- iv) Zirconia (or partially stabilized Zirconia) toughened alumina (ZTA) ceramic
- v) Alumina ceramic reinforced by SiC whiskers
- vi) Silver toughened alumina ceramic

e) Cubic Boron Nitride

f) Diamond Tools

- i) Polycrystalline Diamond (PCD)
- ii) Diamond coated carbide tools